

# K7A

## Převodové elektromotory – komutátorové



Typ	Moment [ Nm ]	Napětí [ V ]	Proud [ A ]	Otáčky [ 1/min ]	Smysl toč.	Převodový poměr	Provoz	Hmotnost [ kg ]
<b>K7A3</b>	0,64	24 =	0,5	45	oba	1 : 98	S1	0,6
<b>K7A8-00</b>	0,64	48 =	0,25	45	oba	1 : 98	S1	0,6
<b>K7A9</b>	0,2	24 =	0,5	140	oba	1 : 32	S1	0,6

